

98180 (NEW)

FITS: YANMAR

GM, GM2, GM3,
GM10, GM20/2-20F,
GM30, GMF, 1GM,
2GM, 3GM

Replaces: HITACHI S114-303,
S114-303A

