

R809

VOLVO PENTA

REPLACES VOLVO PENTA

3858081, 3858809

Volvo Penta (1998 SX-M-MAC, MDA, MLT), 3.0GLP-D, 4.3GL-E, 4.3GL-EF, 4.3GXi-F, 4.3GXi-FF, 4.30Si-F, 4.30Si-FF, 5.0GL-F, 5.0GL-FF, 5.0GXi-F, 5.0GXi-FF, 5.0Si-F, 5.0Si-FF, 5.7Gi-F/FF, 5.7GXi-G/GF, 5.70Si-E/EF, 5.70Xi-E/EF, 5.7Gil-F, 5.7GXi-G, 8.1Gi-G/GF, 8.1GXi-F/FF, 8.10Si-C/CF, 8.1Gil-G, 8.1GXil-F, DPH-A, DPH-B, DPR-A, DPH-B, EF drives, SX-M TSKs 1998-05, SX-M, DP-SM, (WT drives, PJX-C, PJX-S SX-M, -MACLT, -MDA, -MDB, -MHP, -MTD, DP-E, DP-S, -S1, -S2, DP-SM, -SM) XDP-B, O.M.C. COBRAS WITH TELEFLEX PUMPS

