



DO NOT CUT WIRES OR DISMANTLE UNITS

Cutting a unit's wires or dismantling a unit immediately voids the manufacturer's warranty. Water can easily seep into the motor through cut wiring. In addition, taking a motor off the reservoir and trying to install it on an old reservoir usually damages the brushes in the motor. Disassembled parts are not covered by warranty.

6204 (NEW)
 FITS: O.M.C.
 3-wire connection
 2-bolt mount

TR204
 Repair kit



6206 (NEW)
 FITS: O.M.C.
 3-wire connection
 3-bolt mount

TR206
 Repair kit



6208 (NEW)
 (MOTOR/RESERVOIR ONLY)
 FITS: O.M.C.
 3-wire connection

TR208
 Repair kit



To be discontinued when present stock is exhausted.

6209 (NEW)
 FITS: O.M.C.
 2-wire connection

TR209
 Repair kit



6211 (NEW)
 FITS: O.M.C.
 stern-drive 1979-1985
 2.5L, 3.0L
 3-wire connection
 Ring Terminal Ends

TR211
 Repair kit
 (Cast Aluminum)



TR210
 Repair kit
 (Stamped Steel)





REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS

6213 (NEW)
FITS: GOOD AUTOMATIC WINDLASS
Ring Terminal Ends



Will also replace units with this style shaft



6214 (NEW)
MOTOR/RESERVOIR ONLY
FITS: O.M.C.
1979-1985 3.8L, 4.3L, 5.0L, 5.7L
Stern Drive Engines
2-wire connection



To be discontinued when present stock is exhausted.

6216 (NEW)
(MOTOR/RESERVOIR ONLY)
FITS: CHRYSLER, O.M.C.
3-wire connection



6217 (NEW)
(MOTOR/RESERVOIR ONLY)
FITS: B.M.W., MERCUISER, VOLVO PENTA
Includes: Screws, gasket & adapter
Ring Terminal Ends

TAK217
Screws, gasket, adapter



TR217
Repair kit



To be discontinued when present stock is exhausted.

6218 (NEW)
(MOTOR ONLY)
FITS: MERCUISER I/O'S AND MERCURY OUTBOARDS W/OILDYNE PUMP
12 Volt
Ring Terminal Ends



TR218
Brush kit →



6219
24 Volt
Slow speed motor
Fits Jack lift for racing outboards

Replaces early square-style motor



6220 (NEW)
HEAVY-DUTY
FITS: O.M.C.
2-wire connection
Includes O-ring
3-bolt mount
Male Spade Terminal Ends
96" Leads



R473
Relay available



6220X (NEW)
HEAVY-DUTY, FITS: O.M.C.
2-wire connection, Includes O-ring, 3-bolt mount
Male Spade Terminal Ends
62" Leads

6223 (NEW)
HEAVY-DUTY
FITS: VOLVO PENTA
Female Spade Terminal Ends



© ARCO STARTING & CHARGING SPECIALISTS

TOLL FREE 800-722-2720 • PHONE: 850-455-5476 • FAX: 850-453-2630 • WWW.ARCOMARINE.COM

REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS



6224 (NEW)

(COMPLETE)

FITS: VOLVO PENTA

Includes: Hydraulic valve body
Ring Terminal Ends



6225 (NEW)

(MOTOR/ RESERVOIR ONLY)

Fits: PRESTOLITE

To be discontinued
when present stock
is exhausted



← Replaces this style
Prestolite Pump

6228 (NEW)

HEAVY-DUTY

(MOTOR ONLY)

FITS: MANY SMALL

O.M.C. OUTBOARDS

Includes gasket



← Fits: O.M.C. Pump
No. 173946



TR228

Repair kit



To be discontinued
when present
stock is exhausted.

6227 (NEW)

(COMPLETE)

FITS: VOLVO PENTA - THRU 1999

W/OILDYNE PUMP



6232

(MOTOR ONLY)



6231 (NEW)

(MOTOR ONLY)

FITS: U.S. MARINE

W/OILDYNE PUMP

2-wire connection

Female Spade Terminal

Ends

6232 (NEW)

(MOTOR ONLY)

FITS: ARCO 6227,

LATE MODEL

VOLVO PENTA

W/OILDYNE PUMP

2-wire connection



NOTE:

Distance between
mounting bolts: 2.5"
Bolt size: 10x32 fine thread

M531 (NEW)

RESERVOIR KIT

FITS: ARCO 6227

Includes: Reservoir,
cap, and O-ring



Fits Oildyne Pump ONLY

For new style 4 screw
mount see M533 in
miscellaneous section

ARCO STARTING & CHARGING SPECIALISTS ©

TOLL FREE 800-722-2720 • PHONE: 850-455-5476 • FAX: 850-453-2630 • WWW.ARCOMARINE.COM





REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS

6233 (NEW)

FITS: LATE MODEL VOLVO PENTA SX MODELS.

Replaces Teleflex Motor and Volvo part number 3861575



NOTE:
Distance between mounting bolts: 2.3"
Bolt size: 10x24 coarse thread

6237 (NEW)

HEAVY-DUTY FITS: HONDA 2004-Up BF40, BF50

4-bolt mount, Round Plug-In Connector
Includes O-ring
Replaces Honda part number 36120-ZW4-H12



6234 (NEW)

HEAVY-DUTY FITS: HONDA 2002-Up BF200, BF225

4-bolt mount, Round Plug-In Connector
Includes O-ring
Replaces Honda part number 36120-ZY3-013



6238 (NEW)

HEAVY-DUTY Fits: O.M.C. 1998-Up 75 HP-250 HP FFI Outboard Engines
4-bolt mount, Female Sealed Terminal Ends
Includes O-ring



6235 (NEW)

HEAVY-DUTY FITS: HONDA 2004-Up BF135, BF150

4-bolt mount, Round Plug-In Connector
Includes O-ring
Replaces Honda part number 36120-ZY6-013



6236 (NEW)

HEAVY-DUTY FITS: HONDA 2007-Up BF75, BF90

4-bolt mount, Round Plug-In Connector
Includes O-ring
Replaces Honda part number 36120-ZY9-003



6239 (NEW)

HEAVY-DUTY FITS: HONDA 1992-2002 35-50 HP

2-wire connection
Includes O-ring
Hollow-hex shaft
Female Spade Terminal Ends



© ARCO STARTING & CHARGING SPECIALISTS

TOLL FREE 800-722-2720 • PHONE: 850-455-5476 • FAX: 850-453-2630 • WWW.ARCOMARINE.COM

6240 (NEW)

HEAVY-DUTY
FITS: YAMAHA
 1997-UP 115 HP
 2000-UP 115 HP 4-Stroke
 1997-2000 130 HP
 1997-UP 150-200 HP
 1998-UP 225 HP
 2-wire connection
4-bolt mount,
 Ring Terminal Ends
Includes O-ring



6243 (NEW)

HEAVY-DUTY
FITS: O.M.C.
 1989-1992 M-suffix 40, 48, 50 HP
 2-wire connection;
4-bolt mount, Includes O-ring
Hollow-hex shaft
 Male Spade Terminal Ends



R473

Relay available

6244 (NEW)

HEAVY-DUTY
FITS: O.M.C.
 1993 V6
 1993-Up Commercial V8
 2-wire connection;
3-bolt mount,
Includes O-ring
Flat-blade shaft
 Female Spade Terminal End



R473

Relay available

6241 (NEW)

HEAVY-DUTY
FITS: O.M.C. 60, 70, 90,
 115, 150, 175 HP
 1991-Up 200, 225 HP,
 1991-94 120, 140 HP
 1995-Up 50 HP 3-cyl, 60 HP, V4 130 HP
 1997-Up 115-200 HP
 1998-99 225 HP 2-wire connection
4-bolt mount, Flat-blade shaft
 Female Spade Terminal Ends



**Includes O-ring and adaptor to
 replace motors with hollow hex shafts**

R473

Relay available

ALSO REPLACES OEM MOTORS WITH
 HOLLOW HEX SHAFT

6247 (NEW)

HEAVY-DUTY
FITS: EVINRUDE ETEC
 2005-2009 70-90 HP
 2007-2009 115 HP
 2009- 130 HP
 2-wire connection
4-bolt mount, Includes
TAK247 mounting kit,
Flat-blade shaft



TAK247

Mounting bolts, flat washers,
 O-ring and couplers

6242 (NEW)

HEAVY-DUTY
FITS: O.M.C.
 1992-Up J-suffix 40, 48, 50 HP
 2-wire connection
Includes O-ring, 4-bolt mount
Hollow-hex shaft
 Female Spade Terminal Ends



R473

Relay available

6248 (NEW)

HEAVY-DUTY
FITS: EVINRUDE ETEC
 2005-2009 40-50 HP
 2006-2009 60 HP
 2009- 25-30 HP
 2-wire connection
4-bolt mount, Includes
TAK247 mounting kit,
Flat-blade shaft



TAK247

Mounting bolts, flat washers,
 O-ring and couplers



6264 (NEW)
HEAVY-DUTY
FITS: YAMAHA
1985-1992
 40-50 HP
 2-wire connection
4-bolt mount,
Includes O-ring
 Ring Terminal Ends



6268 (NEW)
FITS: SUZUKI
1991-1997 DT90,
1991-2000 DT100,
1991-2003 DT150,
1991-1992 DT175,
1991-2000 DT200,
1991-2003 DT225
 2-wire connection
3-bolt mount
Includes O-ring and adaptor
 Ring Terminal Ends



6265 (NEW)
HEAVY-DUTY
FITS: YAMAHA
1987-1995
 115-200 HP Outboards
1990-1993 225 HP
 2-wire connection
3-bolt mount
Includes O-ring
Flat-blade shaft
 Ring Terminal Ends



6269 (NEW)
FITS: SUZUKI DT 150/200
 3-wire connection
3-bolt mount
Includes O-ring
 Ring Terminal Ends



6266 (NEW)
FITS: YAMAHA
1995-Up 40/50 HP
 2-wire connection
3-bolt mount
Includes O-ring
 Ring Terminal Ends



6270 (NEW)
(COMPLETE)
FITS: Late model MERCURY
 225-275 HP Outboards w/Oildyne pump
 Ring Terminal Ends



6271 (NEW)
(COMPLETE)
 Slow speed unit used for racing applications

6274 (NEW)
HEAVY-DUTY
FITS: Late model MERCURY/MARINER & FORCE 75-125 HP
 outboards w/single ram 3-wire connection;
4-bolt mount
 Hollow-hex shaft
 (Motor/Reservoir Only for Trim Pump Assembly 824051)
Includes stainless steel mounting screws, shaft adaptor, O-ring and fill plug.
 Ring Terminal Ends



6267 (NEW)
FITS: YAMAHA
 Early 70, 90, 115, 150-200 HP
 3-wire connection
3-bolt mount
 Ring Terminal Ends
 4-mm thick shaft blade with 68.3-mm mounting collar.
Includes O-ring





REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS

6275 (NEW)
(COMPLETE)
FITS: Late model MERCUISER
w/Oildyne pump
Ring Terminal Ends



6218 MOTOR ONLY

M525 (NEW)
Reservoir kit
FITS: ARCO 6275
Includes: Reservoir, cap, O-ring,
mounting screw



For new style 4 screw mount
Mercury 883166A2 see M532
in miscellaneous section

6277 (NEW)
HEAVY-DUTY
(MOTOR ONLY)
FITS: ARCO
cartridge pump 6278 only!
2-bolt mount
Ring Terminal Ends



TR277
Repair kit




Motor WILL NOT replace original Mercury pump.

6276 (NEW)
HEAVY-DUTY
FITS: Late model
MERCURY/MARINER, FORCE
40-125 HP outboards
w/single ram
2-wire connection
4-bolt mount
Hollow-hex shaft
(Motor/Reservoir Only)
Includes stainless
steel mounting screws, shaft adaptor,
O-ring and fill plug.
Bullet Connector Terminal Ends




Will also replace these style units



TAK276
Mounting bolts, O-ring, fill cap and
shaft adapters for tilt/trim motors




6279 (NEW)
HEAVY-DUTY
FITS: MERCURY/MARINER
outboards w/Design II
3 ram, three-wire trim units
Hollow-hex shaft
W/AFT FILL RESERVOIR
3-wire connection
2-bolt mount
Shaft adaptor and
O-ring included.
Ring Terminal Ends



AFT FILL RESERVOIR

TR279
Repair kit



© ARCO STARTING & CHARGING SPECIALISTS

TOLL FREE 800-722-2720 • PHONE: 850-455-5476 • FAX: 850-453-2630 • WWW.ARCOMARINE.COM